


FARAD[®] made in Italy

Evolution Srl unipersonale, Via A. De Gasperi 26/A, 12040 Sanfrè (CN) Italy




Instruction manual


KIT PR25 - 6

- | | | | | | |
|----|--|-----------------|---|--|-------------|
| A1 | | | G | | Nr. 4 |
| A2 | | COD. 91141/57 → | H | | Nr. 4 |
| B | | COD. 91141/59 → | I | | M8 → Nr. 4 |
| C | | | L | | M8 → Nr. 4 |
| D | | TCEI 8 x 18 → | M | | Nr. 1 |
| E | | M8 → | N | | M12 → Nr. 4 |
| F | | M8 → | Y | | Nr. 4 |


1




2




3



4




5




6

NO COMPACT




7




NO COMPACT

8




NO COMPACT

9






10



X4





11




FAILURE OBSERVE THIS NOTE CAUSES GLASS BREAKAGE




SUNROOF SIGN




INSIDE RECIVER
Correct fitting



OUTSIDE RECIVER
Wrong fitting




Make sure the clip is well engaged inside the metal receiver under the glass. Clip well fitted must not be able to move back and forth. Repeat this check controll at all 4 fix points









FAILURE OBSERVE THIS NOTE CAUSES GLASS BREAKAGE

12



13





Security Regulations

